

**Attachment A: Digital Images**

Page 1 of 5

August 27<sup>th</sup>, 2008

BOE Building Break Room 807/805 and 22<sup>nd</sup> and 23<sup>rd</sup> Floor Hopper Rooms Areas  
450 N Street, Sacramento, CA



- 1) Image of hallway containment leading to 22<sup>nd</sup> Floor hopper Room area at time of assessment of BOE Building (Subject Building) located at 450 N Street, Sacramento, California.



- 2) Image of area and material removal adjacent to wet-mop sink unit at time of clearance assessment.

August 27<sup>th</sup>, 2008

Page 2 of 5

BOE Building Break Room 807/805 and 22<sup>nd</sup> and 23<sup>rd</sup> Floor Hopper Rooms Areas  
450 N Street, Sacramento, CA



- 3) Image of air sampling equipment and wall removal within mail center room adjacent to 22<sup>nd</sup> floor Hopper Room area at time of assessment.



- 4) Image of air sampling equipment utilized in hallway adjacent to 23<sup>rd</sup> floor Hopper Room area at time of assessment.

August 27<sup>th</sup>, 2008

Page 3 of 5

BOE Building Break Room 807/805 and 22<sup>nd</sup> and 23<sup>rd</sup> Floor Hopper Rooms Areas  
450 N Street, Sacramento, CA



- 5) Image of air sampling equipment and area material removal adjacent to wet-mop sink unit within 23<sup>rd</sup> Floor Hopper Room at time of clearance assessment.



- 6) Image of wallboard removal delineation to left of wet-mop sink area within 23<sup>rd</sup> Floor Hopper Room area at time of assessment.

August 27<sup>th</sup>, 2008

Page 4 of 5

BOE Building Break Room 807/805 and 22<sup>nd</sup> and 23<sup>rd</sup> Floor Hopper Rooms Areas  
450 N Street, Sacramento, CA



- 7) Image of air sampling performed within area occupied by BOE staff adjacent to Break room 807 at time of assessment.




- 8) Image of material removal delineation and exposed plumbing systems within break room 807 at the time of clearance assessment activities.

August 27<sup>th</sup>, 2008

Page 5 of 5

BOE Building Break Room 807/805 and 22<sup>nd</sup> and 23<sup>rd</sup> Floor Hopper Rooms Areas  
450 N Street, Sacramento, CA



- 9) Close-up image of exposed wall cavity as viewed from Conference Room 805 at time of assessment.



- 10) Image from 807 indicating exposed subflooring and delineation of wallboard removal at previous area at the time of assessment.